

### Daily Report of Force Account Worked

**Prime:** Max J. Kuney

**Done by:** 509 EXCAVATING LLC

**Date:** July 24th, 2019

Est. #	Prepared By / Date	Checked By / Date	CAPS Entry By / Date	CAPS Verified By / Date
4	ML 9/18/19	SK 9/18/19	ML 9/18/19	SK 9/18/19



## Daily Report of Force Account Worked

Contract Number C-9385	Date 7/24/2019	Item Number 088	Item Name Roadside Cleanup
Prime Contractor Max J Kuney		Subcontractor/Lower Tier Subcontractor 509 Excavating LLC	
Line / Station JE 26+00 to JE 22+00	Group 01	Basis of Materials Acceptance N/A	RAMS Number N/A

Description of Work Performed

Removing Geotextile material that was excavated from under the existing shoulder while excavating to subgrade. Removing concrete chunks that were broken off the PCCP that was under the existing shoulder when excavating to subgrade.

### Time Worked Record

	Workers and/or Equipment Working	Occupation of Workers or Equipment Size	Labor Hours		Equipment Hours		
			Reg.	O.T.	Reg	Standby	Idle
1	<b>LABOR</b>						
2	Paul Albert	Laborer	5.0				
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							

Calculated By Dean A. Long	Date 8/7/19	Checked By	Date	Total
-------------------------------	----------------	------------	------	-------

Inspector's Signature <i>Dean A. Long</i>	Contractor's Representative Signature <i>[Signature]</i>	Title OPERATIONS MGR
--	---	-------------------------